

▶ | AMF Digital Force Gauge



Features

- 3 measuring modes: real-time mode, peak mode, first peak mode
- Backlight and buzzer alarm
- Automatic power off
- Gravity acceleration setting function
- Set upper and lower limits for statistical analysis
- Minimal force shielding function

Model		AMF-2	AMF-3	AMF-5	AMF-10	AMF-20	AMF-30	AMF-50	AMF-100	AMF-200	AMF-300	AMF-500
Max Loading Value / Load Division Value	N	2/0.001	3/0.001	5/0.001	10/0.01	20/0.01	30/0.01	50/0.01	100/0.1	200/0.1	300/0.1	500/0.1
	kg	0.2 /0.001	0.3 /0.001	0.5 /0.001	1/0.001	2/0.001	3/0.001	5/0.001	10/0.01	20/0.01	30/0.01	50/0.01
	lb	0.45 /0.001	0.65 /0.001	1.1 /0.001	2.2 /0.001	4.5 /0.001	6.5 /0.001	11/0.001	22/0.01	45/0.01	65/0.01	110/0.01
Sensor Structure	Inside											
Accuracy	± 1%											
Storage Temperature	-10°C ~ 60°C											
Operating Temperature	5°C ~ 35°C											
Humidity	15% ~ 80%RH											
Operating Environment	No surrounding source and corrosive medium											
L*H*W (mm)	124*60*31											
Weight	About 0.4kg											
Battery	2*7# batteries (1.5V)											
Units	N, kg, lb, Oz											

▶ | ANC Digital Torque Gauge



Features

- Operation mode: Peak hold mode (P) / Real-time mode (T) / Preset mode (Pre)
- Buzzer and LCD display
- Backlight
- Automatic power off in 10 minutes

Technical Data

Model	ANC-30	ANC-135	ANC-200
Minimum Division Value (N.m)	0.01	0.1	0.1
Max Operation Range (N.m)	3-30	13.5-135	20-200
Square Drive (inches)	1/2		
Accuracy	Clockwise: ± 2% Counterclockwise: ± 2.5%		
Battery	2*7# batteries		